



# TEST REPORT

VF JEANSWEAR  
328 KENNEDY DRIVE  
PUTNAM CT 06260

ATTN: BURT ELLIOTT  
CC: NONE

LAB NO.: (6507) 284-0065  
FORM NO.: N/L  
DATE IN: OCTOBER 11, 2007  
MODIFIED DATE IN: -  
DATE OUT: OCTOBER 16, 2007  
DIVISION: N/L  
DEPARTMENT: N/L  
CATEGORY: N/L  
BUYER: N/L  
NO. OF WORKING DAYS: 3  
PAGE: PAGE 1 OF 3

OVERALL RATING	
PASS	_____
FAIL	_____
DATA	_____X_____

<b>Vendor:</b>	VF Jeanswear	<b>Agent:</b>	N/L
<b>Fabric Supplier/Mill:</b>	N/L	<b>Factory/Manufacturer:</b>	US Button Corp.
<b>P.O. No.:</b>	N/L	<b>Style No.:</b>	Asst.
<b>Sample Description:</b>	One (1) Sample Of Melamine Button	<b>Style Description:</b>	N/L
<b>Color:</b>	N/L	<b>Country of Origin:</b>	USA
<b>Claimed Fabric Weight:</b>	N/L	<b>Claimed Fabric Count:</b>	N/L
<b>Yarn Size:</b>	N/L	<b>Submitted Size:</b>	N/L
<b>Size Range:</b>	N/L	<b>FPU No.:</b>	N/L
<b>GPU No.:</b>	N/L	<b>End Use:</b>	Shirts

<b>Product Category:</b>	Buttons
<b>Test Requested:</b>	Lead and Nickel Content
<b>Previous Report No.:</b>	N/A

<b>Submitted Fiber Content:</b>	N/L
<b>Actual Fiber Content:</b>	N/R
<b>Suggested Fiber Content:</b>	N/R
<b>Submitted Care Instruction(s):</b>	N/L
<b>Client Expected Care Instruction:</b>	N/L
<b>Suggested Care Instruction(s):</b>	N/R



**BUREAU  
VERITAS**

TEST PROPERTY	PASS	FAIL	DATA	
LEAD CONTENT			X	
NICKEL TEST			X	

**TEST PROPERTY**

**TEST RESULTS**

**LEAD CONTENT**(ASTM E1645/E1613 MODIFIED)

Z71 NEW YUKON (M 2213)	< 12
Z31 PEROT (M 2138)	< 9
Z31 PEROT (M 4407)	< 5
NIAGARA TWIN (M 7441)	< 6
NIAGARA TWIN (M 1708)	< 9
NIAGARA TWIN (M 9702)	< 9

**NICKEL SPOT**(ASTM E1645/E1613 MODIFIED)

Z71 NEW YUKON (M 2213)	< 12
Z31 PEROT (M 2138)	< 9
Z31 PEROT (M 4407)	< 5
NIAGARA TWIN (M 7441)	< 6
NIAGARA TWIN (M 1708)	< 9
NIAGARA TWIN (M 9702)	< 9



**KEYS:**

N/A: Not Applicable  
N/R: Not Requested  
N/L: Not Listed  
I/S: Insufficient Sample

---

Client Specialist  
Debby Pereira

---

Reviewer

For any questions please contact Yvonne Hanna  
[Yvonne.Hanna@us.bureauveritas.com](mailto:Yvonne.Hanna@us.bureauveritas.com)  
1-508-844-2757